

Low River Slope Improvements - aerial photos of project site  
May 8, 2017.



Area where work is  
to take place.

Looking upstream on the Lowe River, Alpine  
Woods on the left of the photo.



Overhead view of groin #4 and the eroded area that will be reinforced with riprap.





An oblique view of groin #4 looking upstream at the area to receive riprap.