



Photo taken during the outburst flood and how it prevented a repeat of the previous year's flooding.

Here's a photo of the start of the 700' long ditch we excavated and filled with riprap across from the landfill. The river is currently right next to it and may even expose the buried rock this fall.

